

Main Road	Minor Road/s	Town/Village	Issue	Potential Solution
Elms Rd	Dorchester Rd & Nightingale Grd	Hook	Parked vehicles obstructing visibility	Junction protection through introduction of double yellow line prohibitions
Medlar Drive	Hawley Road	Blackwater	School parents parking within junction reducing safety, and obstructing access	introduce junction protection with restrictions
Sandy Lane (Jubilee Drive)		Church Crookham	Vehicles being parked by on Sandy Lane, restricting traffic flows	School peak period parking controls
Bartley Way		Hook	Overnight HGV parking in residential areas	Introduce overnight parking prohibition for HGVs over 7.5t
Southby Drive		Fleet	Vehicles parking near junction and long narrow section	Introduce prohibition to protect junctions
A30 London Road	Sheldons Lane	Hook	Vehicles parking on the westbound A30 causing westbound traffic to pass by diverting into the right turn bay and central hatching, causing increased detrimental risk of collision between traffic	Introduce double yellow lines on westbound A30 over extent of right turn bay from crossing point adjacent to Catholic Church in east to end of taper in west
Mitchell Avenue	St Mary's Road	Hartley Wintney	Congestion caused by parking for junior football on Saturday mornings in Jubilee Fields	Double yellow lines around the junction back to the crossing
Dilly Lane		Hartley Wintney	An increase of traffic from recent developments travelling along Dilly Lane with fewer passing places due to on-street parking from local businesses and residents	Introduced localised prohibitions and restrictions
Willowbourne		Fleet	Traffic parking in vicinity of local buildouts and along section of road reducing available passing places	Introduced localised prohibitions around the traffic management buildout
Willowbourne	Alder Court	Fleet	Traffic parking in a manner obstructing refuse collection	Introduced localised prohibitions
Willowbourne	Hitches Lane	Fleet	Willowborne between Alder Court and Hitches Lane, obstructing access to Edenbrook	Introduced localised prohibitions
Palace Gate		Odiham	Long stay parking along Palace Gate causing vehicles to mount and damage highway verge	Introduced localised prohibitions
B3349 Griffin Way South	Station Road	Hook	Vehicles parking on footway and verge obstructing footway for all users	Introduced localised prohibitions
Blaire Park		Yateley	Residents parking in advisory disable bay in congested street	Enforceable disabled parking bay
Reading Road South	Ryelaw Road	Church Crookham	Sole traders and utility vans being parked overnight and at weekends between Chilern Close and RRS obstructing traffic movements and clear visibility of the junction from Ryelaw Rd to RRS, and obstructing vehicles movements from RRS into Ryelaw Road	Prohibition of waiting on approach to junction for 25-metres between Chilern Cl and RRS

Main Road	Minor Road/s	Town/Village	Issue	Potential Solution
Bramshott Lane			Disable users to Bramshott Country Park have restricted access due to over-height vehicles, placing wheelchair bound visitors in danger	Introduce an enforceable disable bay to enable over-height vehicles only
Church Lane	Chatter Alley	Dogmersfield	Vehicles being parked along Church Lane reducing width to single lane and obstructing junctions, and vehicles parking in close vicinity to the Church Lane/Chatter Alley junction obstructing forward visibility and reducing the safety of the junction	Introduce localised prohibitions and restrictions
Albert Street		Fleet	HGV waiting to access Travis Perkins are obstructing private access and visibility	
Albert Street		Fleet	Lack of resident parking due to parking by visitors to Fleet Road and other businesses	Review bay provision between Church Road and Reading Road South and revert bays to resident permit holder only
Darset Avenue		Fleet	Short length of double yellow line combined with high neighbour hedge obstructing visibility for vehicles as they manoeuvre around parked vehicles on single yellow lines	Extend double yellow lines to be 30-metres in length from junction to ensure approach to Fleet Rd junction is clear and visible